Autonics

Color Mark Sensor
BC SERIES

INSTRUCTION MANUAL

CE

Thank you for choosing our Autonics product.
Please read the following safety considerations before use.

Safety Considerations

※Please observe all safety considerations for safe and proper product operation to avoid hazards.
※⚠ symbol represents caution due to special circumstances in which hazards may occur.

⚠ **Warning** Failure to follow these instructions may result in serious injury or death.
⚠ **Caution** Failure to follow these instructions may result in personal injury or product damage.

⚠ Warning

1. **Fail-safe device must be installed when using the unit with machinery that may cause serious injury or substantial economic loss. (e.g. nuclear power control, medical equipment, ships, vehicles, railways, aircraft, combustion apparatus, safety equipment, crime/disaster prevention devices, etc.)**
Failure to follow this instruction may result in personal injury, economic loss or fire.
2. **Do not use the unit in the place where flammable/explosive/corrosive gas, high humidity, direct sunlight, radiant heat, vibration, impact, or salinity may be present.**
Failure to follow this instruction may result in explosion or fire.
3. **Do not disassemble or modify the unit.**
Failure to follow this instruction may result in fire.
4. **Do not connect, repair, or inspect the unit while connected to a power source.**
Failure to follow this instruction may result in fire.
5. **Check 'Connections' before wiring.**
Failure to follow this instruction may result in fire.

⚠ Caution

1. **Use the unit within the rated specifications.**
Failure to follow this instruction may result in fire or product damage.
2. **Use dry cloth to clean the unit, and do not use water or organic solvent.**
Failure to follow this instruction may result in fire.

Model

Model	Item	Sensing distance	Sensing method	Power supply	Output type	Connection	Control output
BC15-LDT-C	Color mark sensor	15mm	Convergent reflective type	12-24VDC	Solid state output (transistor)	Connector type	NPN open collector output
BC15-LDT-C-P							PNP open collector output

Control Output Circuit Diagram

NPN open collector output

(brown) +V
Load
(black) Output
12-24VDC
Output short over current protection circuit
Main circuit
(blue) 0V
(white) SET

PNP open collector output

(brown) +V
Output short over current protection circuit
(black) Output
12-24VDC
Load
Main circuit
(blue) 0V
(white) SET

※If short-circuit the control output terminal or supply current over the rated specification, normal control signal is not output due to the output short over current protection circuit.

Connections for Connector Part

Pin number	Color code	Application
1	Brown	+V
2	White	SET
3	Blue	GND (0V)
4	Black	OUT

④ ③
① ②

M12 connector Pin

●**Connector cable (sold separately)**
※Connector cable model
: CIDH4- □
(connector length □: 2, 3, 5, 7m)

※Please use Autonics M12 connectors.
For more information, please refer to our catalogue or website.

※**The above specifications are subject to change and some models may be discontinued without notice.**
※**Be sure to follow cautions written in the instruction manual and the technical descriptions (catalog, homepage).**

Specifications

Model	BC15-LDT-C	BC15-LDT-C-P
Sensing method	Convergent reflective type	
Sensing distance	15mm ±2mm	
Sensing target	Opaque, Translucent	
Hysteresis	Max. 20% of sensing distance (may vary by sensing mode or sensitivity)	
Spot size	1.24×6.7mm (rectangular)	
Response time	500μs	
Power supply	12-24VDC═ ±10% (ripple P-P: max. 10%)	
Current consumption	Max. 30mA	
Light source	Full Color LED (red, green, blue)	
Sensing mode	C (color only) mode, C+I (color + intensity) mode	
Output mode	Color match output, color mismatch output	
Output timer	40ms OFF delay timer function	
Control output	NPN or PNP open collector output · Load voltage: max. 30VDC═ · Load current: max. 100mA · Residual voltage - NPN: max. 1VDC═, PNP: max. 2.5VDC	
Protection circuit	Reverse polarity protection, output short over current protection	
Indicator	Operation indicator: Red LED, Stability indicator: Green LED, Teaching indicator: Full Color LED	
Connection method	Connector type	
External input	External SET cable input	
Insulation resistance	Over 20MΩ (at 500VDC megger)	
Noise immunity	±240V of square wave noise (pulse width:1 μs) from the noise simulator	
Dielectric strength	1,000VAC at 50/60Hz for 1minute	
Vibration	1.5mm amplitude at 10 to 55Hz frequency in each X, Y, Z direction for 2 hours	
Shock	500m/s² (approx. 50G) in each X, Y, Z direction for 3 times	
Environment	Ambient illumination	Incandescent lamp: Max. 3,000lx (receiver illumination)
	Ambient temp.	-10 to 55℃, storage: -25 to 75℃
	Ambient humi.	35 to 85%RH, storage: 35 to 85%RH
Protection structure	IP67 (IEC standard)	
Material	Case: Polycarbonate, Sensing part: Acrylic, Bracket: SUS304 (steel use stainless 304) , Bolt: Carbon steel	
Accessories	Bracket, M3 bolts: 2, Adjustment screwdriver: 1	
Approval	CE	
Weight[※1]	Approx. 80g (approx. 14g)	

※1: The weight includes packaging. The weight in parenthesis is for unit only.
※The temperature and humidity of environment resistance is rated at non-freezing or condensation.

Unit Description

1. Operation indicator (OUT): ON (red) indicates operation.
2. Stability indicator (STB): ON (green) indicates stable status.
3. Timer indicator (TMR): ON (orange) when timer is set.
4. Teaching indicator
: Displays the reference color after successfully "teaching" the color.
※The teaching color and the color displayed on the teaching indicator may differ depending on environment conditions (ambient light, reflection angle, material, etc.) .
5. SET key: Used for function settings.
6. Color match/mismatch switch
- N.O.: Output ON when target color matches reference color.
- N.C.: Output ON when target color does not match reference color.

Dimensions

(unit: mm)

Optical axis Receiver
Optical axis Emitter
2-M3 Tap
16
5.8
37
25.4
5.8
16.5
49.2
11.2
6.5
19.8
28
M12 Tap

Operation indicator(red)
Stability indicator (green)
Timer indicator (orange)
Teaching indicator

●**Mounting Bracket**

28
R22
R2
30°
30°
9.4
20
4-R1.6
6-Ø3.2
25.4
25.4
40
21.5
8.8
1.2

Functions

Color teaching
Set the reference color with the teaching function. Press the SET key in RUN mode to enter teaching standby status. Place the desired color at the sensing position (spot) and hold the SET key for over 3 seconds.
When teaching is complete, the teaching color indicator will turn ON.
When there is an error, the operation indicator will flash (red).

Display teaching
The set reference color can be displayed on the teaching indicator.
With the ability to check the set reference color there is no need to re-set the teaching color every time. It may difficult to check the similar colors when installing multiple sensors.
Teaching indicator color is available only for reference.
※The teaching color and the color displayed on the teaching indicator may differ depending on environment conditions (ambient light, reflection angle, material, etc.).

Sensing mode, sensitivity setting (color tolerance)
Two sensing modes; C (color only) mode discriminates by color rate and C+I (color +intensity) mode discriminates by color rate and contrast.
Set the sensing sensitivity (fine, normal, rough) at each sensing mode.

Color match/mismatch mode
- Color match mode (N.O.): Output ON when target color matches reference color.
Turn the color match/mismatch switch towards N.O.
- Color mismatch mode (N.C.): Output ON when target color does not match reference color.
Turn the color match/mismatch switch towards N.C.

OFF delay timer
Timer (40ms OFF delay) functions helps prevent output malfunction from target objects moving too rapidly. The timer indicator turns ON (orange) when the timer function is set.

Operation and Settings

Start teaching ←SET over 3 sec→ Teaching standby ←SET over 3 sec→ RUN mode ←SET over 5 sec→ Timer setting
SET ← → SET ← → SET over 1 sec

SET over 3 sec
↓
Sensing mode, sensitivity setting

RUN mode

Teaching
Teaching standby

	OUT	STB	Teaching indicator
	●	●	(orange)

Start teaching

	OUT	STB	Teaching indicator
Normal	☼	☼	(teaching color)
Error	◑		☼[※2]

Timer setting
Timer ON

	OUT	STB	TMR
	◑	●	☼

Timer OFF

	OUT	STB	TMR
	◑	●	●

Sensing mode, sensitivity setting
C mode: Fine

	OUT	STB	Teaching indicator
	●	●	(Red)

C mode: Normal

	OUT	STB	Teaching indicator
	◑	●	(Green)

C mode: Rough

	OUT	STB	Teaching indicator
	◑	●	(Blue)

C+I mode: Fine

	OUT	STB	Teaching indicator
	●	●	(Red)

C+I mode: Normal

	OUT	STB	Teaching indicator
	●	◑	(Green)

C+I mode: Rough

	OUT	STB	Teaching indicator
	●	◑	(Blue)

※Indicator status
☼	OFF
◑	Flashing (every 0.5 sec)
☼	ON

※Settings can be configured externally using SET cable.
※1: After teaching is complete, the unit will return to RUN mode automatically.
When there is no SET input for 10 seconds during teaching standby, the unit will return to RUN mode.
※2: Light color varies depending on error type. Please refer to "■ Indicator Display".

Indicator Display

Status		Operation indicator (Red LED)	Stability indicator (Green LED)	Teaching indicator (Full color LED)	Timer indicator (Orange LED) Timer ON	Timer OFF
Normal operation	Stable match	☼	☼	☼ (Teaching color)		
	Unstable match	☼	●			
	Unstable mismatch	●	●			
	Stable mismatch	●	☼			
Sensitivity setting (C mode)	Fine	◑	●	◑ (Red)		
	Normal			◑ (Green)		
	Rough			◑ (Blue)		
Sensitivity setting (C+I mode)	Fine	●	◑	◑ (Red)		
	Normal			◑ (Green)		
	Rough			◑ (Blue)		
Teaching setting	Teaching standby	●	●	● (Orange)		
	Normal teaching	☼	☼	☼ (Teaching color)		
	Teaching error	Excess light intensity	◑	●	◑ (Green)	
		Insufficient light intensity	◑	●	◑ (Red)	
		Fluctuating light intensity	◑	●	◑ (Blue)	
Timer setting	ON	◑	◑	☼ (Teaching color)	☼	
	OFF	◑	◑	☼ (Teaching color)		●
Overcurrent input		▶	◀			

※Indicator status
☼	ON	●	OFF
◑	Flashing (every 0.5 sec)	▶◀	Flashing alternately (every 0.5 sec)

Operation Mode

Match rate
Teaching value
Hysteresis
Sensitivity

Stability indicator (green LED)	ON/OFF
Operation indicator (red LED)	ON/OFF
Transistor output	ON/OFF

※The waveforms of "Operation indicator" and "Transistor output" are for color match mode operation. They are opposite operation for color mismatch mode operation.

Installation and Adjustment

①Installation
: Place the color mark sensor and the target object facing each other then affix the unit. The installation distance should be within ±2mm of 15mm.
②Press the SET key to enter teaching standby status. Place the desired color at the sensing position (spot) and hold the SET key for 3 seconds to set the reference color. When it is complete, the teaching indicator will display the set color
③Hold the SET key for 3 seconds change sensing mode and sensitivity settings.
④Hold the SET key for 5 seconds to set the timer.
The timer is a 40ms OFF delay timer.

Within 15±2mm

※In case of teaching error, the output indicator and teaching indicator will flash depending on the intensity of received light.
※When detecting metal or glossy objects tilt install the sensor at about 10 to 20 degree angle.
※When using photoelectric sensors closely over two units, it may result in malfunction due to mutual interference.
※When installing the product, tighten the screw with a tightening torque of 0.8N·m.

Troubleshooting

Problem	Cause	Troubleshooting
Will not operate	Power supply	Supply power within rated specifications
	Connection error	Check the cable connections.
Will not operate occasionally	Excess light intensity alarm during teaching, output chattering	Install the sensor at a 10 to 20 degree angle. (when sensing metal or glossy objects)
	Converter external light interference	Install a visor on the sensor or install the unit away from the external light source.
	Contamination of sensor cover	Remtove the substance using a soft brush and reset the sensitivity.
	Connector error	Check connector assembly.
Other error		Check the display status of the indicators.

Cautions during Use

1. Follow instructions in 'Cautions during Use'. Otherwise, it may cause unexpected accidents.
2. When connecting a DC relay or other inductive load to the output, remove surge by using diodes or varistors.
3. Use the product, 0.5 sec after supplying power.
When using separate power supply for the sensor and load, supply power to sensor first.
4. 12-24VDC power supply should be insulated and limited voltage/current or Class 2, SELV power supply device.
5. Wire as short as possible and keep away from high voltage lines or power lines, to prevent inductive noise.
6. When using switching mode power supply to supply the power, ground F.G. terminal and connect a condenser between 0V and F.G. terminal to remove noise.
7. When using sensor with the equipment which generates noise (switching regulator, inverter, servo motor, etc.), ground F.G. terminal of the equipment.
8. This unit may be used in the following environments.
①Indoors (in the environment condition rated in 'Specifications')
②Altitude max. 2,000m
③Pollution degree 2
④Installation category II

Major Products

■ Photoelectric Sensors
■ Fiber Optic Sensors
■ Door Sensors
■ Door Side Sensors
■ Area Sensors
■ Proximity Sensors
■ Pressure Sensors
■ Rotary Encoders
■ Connectors/Sockets
■ Switching Mode Power Supplies
■ Control Switches/Lamps/Buzzers
■ I/O Terminal Blocks & Cables
■ Stepper Motors/Drivers/Motion Controllers
■ Graphic/Logic Panels
■ Field Network Devices
■ Laser Marking System (Fiber, CO₂, Nd: YAG)
■ Laser Welding/Cutting System

■ Temperature Controllers
■ Temperature/Humidity Transducers
■ SSRs/Power Controllers
■ Counters
■ Timers
■ Panel Meters
■ Tachometer/Pulse (Rate) Meters
■ Display Units
■ Sensor Controllers

Autonics Corporation

http://www.autonics.com

■ HEADQUARTERS:
18, Bansong-ro 513 beon-gil, Haeundae-gu, Busan, South Korea, 48002
TEL: 82-51-519-3232
■ E-mail: sales@autonics.com

DRW161037AC