OMRON

Sensing	distance	Supply voltage	Output
~ \$= 1 ,		10 to 30 VDC	\prec
(Optical fiber series)			80 mA, 100 mA

Photoelectric Sensor

E3S-X

Fiber Optics Amplifier Unit with a Rugged Metal Housing

- Wide variety of fiber units allow detection in a limited space.
- Easy adjustment with LIGHT and STABILITY indicators.
- High-speed response time of 1 ms essential for sensing minute objects is provided.
- Mutual interference protective circuit allows side-by-side mounting of two fiber units.



Ordering Information

Amplifier Unit

Output	Model
NPN	E3S-X3CE4
PNP	E3S-X3CB4

Optical Fiber Units

To order optical fiber units, refer to the E32 Datasheet (E48-E1).

Specifications -

■ Ratings/Characteristics


Power supply voltage			12 VDC -10% to 24 VDC +10%; ripple (p-p): 10% max.	
Current consumption			50 mA max.	
Control output	DC solid-state Load E4 (NPN): 80 mA max. B4 (PNP): 100 mA max.			
		Voltage output	2.0 V max.	
Response time (ON, OFF)		FF)	1 ms max.	
Sensitivity			Adjustable	
Operation mode			Wire-selectable (Refer to "Output Circuits")	
Indicators			Light indicator (red), stability indicator (green)	
Mutual interference protection		otection	Provided	
Enclosure rating			IEC144: IP66 NEMA: 1, 3, 4X, 12	
Housing material			Metal	
Light source			Infrared LED	
Ambient temperature			Operating: -25 to 55 °C	

Operation

■ Output Circuits


E3S-X3CE4 (NPN Output)

E3S-X3CB4 (PNP Output)




■ Timing Chart

E3S-X3CE4 (NPN Output)



E3S-X3CB4 (PNP Output)




Dimensions

Note: All units are in millimeters unless otherwise indicated.

E3S-X3C□4

Cord: Polyvinyl chloride-covered cord 4.3C x 0.2-mm dia., 18/0.12 Standard length: 2 m



Mounting Holes

Note: A mounting bracket can be attached to side A.


Precautions

Mounting the Fiber Unit

Plastic Fiber

To connect the fiber unit with the amplifier unit, insert the two cable ends of the fiber unit into the head of the amplifier unit, and sandwich them between the head and the cover fitting. Secure the cover fitting with the M3 screw.

If the fibers are not inserted completely, sensing distance may be shortened.



ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.

Cat. No. E05-E1-8 In the interest of product improvement, specifications are subject to change without notice.

OMRON Corporation

Sensing Components & Systems Division 28th Fl., Crystal Tower Bldg. 1-2-27, Shiromi, Chuo-ku, Osaka 540 Japan

Phone: 06-949-6012 Fax: 06-949-6021

Printed in Japan 0895-0.5M (0895) a