

Cable color
Brown
Blue
Black
White
Orange
Shield
N·C

+V

lov

OUT

OUT


OUT F.G.


N-C

## O Line driver output



Pin No.	Function	Cable color
1	+V	Brown
2	0V	Blue
3	OUTA	Black
4	OUTĀ	Red
5	F.G.	Shield
6	OUT B	White
0	OUT B	Gray
8	OUT Z	Orange
9	OUTZ	Yellow
10	N·C	N·C





1. Follow instructions in 'Cautions during Use'. Otherwise, it may cause unexpected accidents.

2. 5VDC, 12-24VDC power supply should be insulated and limited voltage/current or Class 2, SELV power supply

3. For using the unit with the equipment which generates noise (switching regulator, inverter, servo motor, etc.),

5. When using switching mode power supply, frame ground (F.G.) terminal of power supply should be grounded. 6. Wire as short as possible and keep away from high voltage lines or power lines, to prevent inductive noise.

7. For Line driver unit, use the twisted pair wire which is attached seal and use the receiver for RS-422A communication. 8. Check the wire type and response frequency when extending wire because of distortion of waveform or residual voltage increment etc by line resistance or capacity between lines.



E-mail: sales@autonics.con

DRW171374AB